


# Digital Kitchen scale

## VK-4C

## VISIONTECH SHOP



### Specification

Model no: VK-4C  
Capacity: 10lb/160oz/5kg/5000g  
Tare range: 100% F.S  
Zero range: 4% F.S  
Unit : lb/oz/kg/g


Platter Size(inch/mm): 6.5(W) x 5.9(D)/ 165(W) x 150(D)mm  
Product Size(inch/mm): 7.5(W) x 9.8(D) x 2.2(H)/190(W) x 250(D) x 56(H)mm  
Operating Temperature: 32°F~104°F / 0°C ~40 °C  
Power: 3VDC(2 x AA batteries)  
Division: 0.002lb/0.5oz/0.001kg/1g

### Function keys

- 1.Press on/off key,turn on the scale, enter into normal weighing status. The screen will display full capacity before the screen display zero.
- 2.Press unit key, to select the weighing unit under normal weighing status
- 3.Press on/off key,turn off the scale



### ALARM

Warning message	Reason	Solution
Display "Err"	Exceed max capacity	Take away the over-weightobject
Battery symble "  " flashing	Not enough power	Change new battery


## Operation



① power on



② put the container on the pan, display "0.005lb"



③ press "tare" key to tare the container's weight, display "0.000lb"



④ put the object in the container, display "1.000lb"




⑤ power off

## Unit Select



①



②



③



④



⑤

## NOTE

1. Use the scale on the stable level surface
2. No overloading
3. Forbid to drech, washing, keep the body inside dry, don't fall off the scale
4. When it indicates low power ,please replace new battery
5. Clean the scale with mild detergent ,chemicals is not allowed.
6. If it is incorrect, it needs to recalibrate by standard weight or contact with dealer

VISION<sup>TECH</sup><sub>SHOP</sub> VisionTechShop.com

100 Temple Ave. Hackensack, NJ 07601

Tel: +1-201-679-7793